

Data Erasure Report



Customer Details

Customer Name:

Customer Location:

Operator Details

Erasure Provider: Licitante

Erasure Technician:

Custom Fields

Custom 1:

Campos Personalizables 2.1.12

Custom 2:

Campos Personalizables 2.1.12

Erasure Results

Disk: 1 (1-1)

Vendor: HP

Size: 300GB

HPA: Doesn't exist

Health Status: good

2.1.7, DCO/HPA

Model: EH0300JDYTH

Bus: SAS

DCO: Doesn't exist

2.1.3

Serial: 0TV52MYJ

Sectors: 585937500

Remapped Sector(s): 0

Remapped Sector(s) After Erasure:

0

Start/End Time:

2019-12-03 18:10:07 (+0000) / 2019-12-03 18:43:13 (+0000)

Duration:

00:33:06

Method:

HMG Infosec Standard 5, Lower Standard → 2.1.2 Estándar Internacional

Erasure Rounds:

1 (1 overwriting)

Status:

Erased

Disk: 2 (1-2)

Vendor: HP

Size: 300GB

HPA: Doesn't exist

Health Status: good

Model: EH0300JDYTH

Bus: SAS

DCO: Doesn't exist

Serial: 0TV574YJ

Sectors: 585937500

Remapped Sector(s): 0

Remapped Sector(s) After Erasure:

0

Start/End Time:

2019-12-03 18:10:07 (+0000) / 2019-12-03 18:42:35 (+0000)

Duration:

00:32:28

Method:

HMG Infosec Standard 5, Lower Standard → 2.1.2 Estándar Internacional

Erasure Rounds:

1 (1 overwriting)

Status:

Erased

Hardware Details

→ III.3.C.2 Estado del Hardware

Manufacturer:

HP

Chassis Type:

Rack Mount Chassis

Model:

ProLiant DL380 Gen9

Serial:

USE527SX88

UUID:

30393137-3136-5355-4535-323753583838

System SKU Number:

719061-B21

Processors:

Physical CPUs: 2, Cores: 24

Processor:

GenuineIntel, Intel(R) Xeon(R) CPU E5-2680 v3 @ 2.50GHz, Cores: 12, Stepping: 2, Nominal speed: 2500MHz, Max speed: 3300MHz, External Clock: 100 MHz, Voltage: 2.3 V

Processor:

GenuineIntel, Intel(R) Xeon(R) CPU E5-2680 v3 @ 2.50GHz, Cores: 12, Stepping: 2, Nominal speed: N/A, Max speed: 3300MHz

Memory Bank:

HP, 16GB, 2133MHz, DDR4, DIMM

Memory Bank:

HP, 16GB, 2133MHz, DDR4, DIMM

Memory Bank:

Unknown Vendor, Empty slot, DIMM

Memory Bank:

HP, 16GB, 2133MHz, DDR4, DIMM

Memory Bank:

HP, 16GB, 2133MHz, DDR4, DIMM

Memory Bank:

Unknown Vendor, Empty slot, DIMM

Memory Bank:

Unknown Vendor, Empty slot, DIMM

Memory Bank:

HP, 16GB, 2133MHz, DDR4, DIMM

Memory Bank:

HP, 16GB, 2133MHz, DDR4, DIMM

Memory Bank:

Unknown Vendor, Empty slot, DIMM

Memory Bank:

HP, 16GB, 2133MHz, DDR4, DIMM

Memory Bank:

HP, 16GB, 2133MHz, DDR4, DIMM

Memory Bank:

HP, 16GB, 2133MHz, DDR4, DIMM

Memory Bank:

HP, 16GB, 2133MHz, DDR4, DIMM

Memory Bank:

Unknown Vendor, Empty slot, DIMM

Memory Bank:

HP, 16GB, 2133MHz, DDR4, DIMM

Memory Bank:

HP, 16GB, 2133MHz, DDR4, DIMM

→ III.3.C.2 No de Serie

Memory Bank: Unknown Vendor, Empty slot, DIMM
Memory Bank: Unknown Vendor, Empty slot, DIMM
Memory Bank: HP, 16GB, 2133MHz, DDR4, DIMM
Memory Bank: HP, 16GB, 2133MHz, DDR4, DIMM
Memory Bank: Unknown Vendor, Empty slot, DIMM
Memory Bank: HP, 16GB, 2133MHz, DDR4, DIMM
Memory Bank: HP, 16GB, 2133MHz, DDR4, DIMM
Total Memory: 256GB, Occupied memory banks: 16/24
Graphics Card: Matrox Electronics Systems Ltd. MGA G200EH / Hewlett-Packard Company iLO4, 16MB
Storage Controller: 1 Hewlett-Packard Company P840
Storage Controller: 2 QLogic Corp. ISP2532-based 8Gb Fibre Channel to PCI Express HBA / Hewlett-Packard Company StorageWorks 82Q
Storage Controller: 3 QLogic Corp. ISP2532-based 8Gb Fibre Channel to PCI Express HBA / Hewlett-Packard Company StorageWorks 82Q
Disk: 1 (1-1) HP, EH0300JDYTH, Firmware: HPD1, Serial: 0TV52MYJ, 300GB / 585937500 sector(s), SAS, Sector Size: 512, Average Write Speed: 146MB/s, Average Read Speed: 153MB/s, Accessible Region: 300GB / 585937500 sector(s), DCO: Doesn't exist, HPA: Doesn't exist, Health Status: good
Disk: 2 (1-2) HP, EH0300JDYTH, Firmware: HPD1, Serial: 0TV574YJ, 300GB / 585937500 sector(s), SAS, Sector Size: 512, Average Write Speed: 149MB/s, Average Read Speed: 157MB/s, Accessible Region: 300GB / 585937500 sector(s), DCO: Doesn't exist, HPA: Doesn't exist, Health Status: good
Network Adapter: Ethernet, Broadcom Inc. and subsidiaries NetXtreme BCM5719 Gigabit Ethernet PCIe / Hewlett-Packard Company Ethernet 1Gb 4-port 331i Adapter, 3c:a8:2a:1e:cf:bb
Network Adapter: Ethernet, Broadcom Inc. and subsidiaries NetXtreme BCM5719 Gigabit Ethernet PCIe / Hewlett-Packard Company Ethernet 1Gb 4-port 331i Adapter, 3c:a8:2a:1e:cf:b9
Network Adapter: Ethernet, Broadcom Inc. and subsidiaries NetXtreme BCM5719 Gigabit Ethernet PCIe / Hewlett-Packard Company Ethernet 1Gb 4-port 331i Adapter, 3c:a8:2a:1e:cf:ba
Network Adapter: Ethernet, Broadcom Inc. and subsidiaries NetXtreme BCM5719 Gigabit Ethernet PCIe / Hewlett-Packard Company Ethernet 1Gb 4-port 331i Adapter, 3c:a8:2a:1e:cf:b8
USB Device: Lenovo, Unknown model (0x6099), Lenovo, Lenovo Traditional USB Keyboard 2.00
USB Device: Unknown Vendor (0xffff), Unknown model (0x5678), USB, Disk 2.0 2.00
BIOS: HP, Version: P89, Date: 05/06/2015
BIOS Features: PCI, PNP, ACPI, CD Boot, EDD, Legacy USB
Ports: USB Ports: 6, Serial Port: 1

Report Details

Report UUID: cb792259-e506-412c-a213-1025cd8dca46
Report Date: 2019-12-03 18:45:01 (+0000)
Software Version: Blancco Drive Eraser 6.10.0

Digital Signature:

TVbaiy79cefq7F8RyhpOxOHEMC1VyNT1vd23ANsnHVaF2qyz9f7J8x2CSq/BixOhtEE3v+RF7zF0LmeV8ojrez9vtaCrUfNujtMx3ukNNDBlAqv/KaWrGj1Junq6Kt+Lq6jpxzWrGoP0JYy7Alo6XAIFBgnG8H7lWutNnDrQbfV
JOhw8+xpex56VYzA2sz+o4drdn071zKIME8ythEW/POC2kAmYKnQ3Yao8J+7Gsx9wIG80WgJZ+IqYjEcmibRy3wNDk7NrQrVgS+XayaOioF3yj6owCmdD1zsoSZUhsd+gN7l5jBE1nZsDjhhp43j9hQ8J/r2LUqJ9hQ==

→ 2.1.8 y 2.1.9 Encriptación SHA-256

I hereby state that the data erasure process has been carried out in accordance with the given instructions.

DATA ERASURE OPERATOR

SUPERVISOR